

REPRO HANDHELD LIGHTS REPRO HANDHELD LIGHTS

USER'S MANUAL

ヴィンテージ・ハンドヘルド・ランプ

取扱説明書

MODEL: 40SHB



LIST OF ACCESSORIES

You will receive the following accessories (subject to the options available at the time of your order)





- 1 Handheld light
- 2 Silicone softbox
- Mobile phone clip (horizontal / vertical)


- 4 Battery charger
- **6** Camera bracket (mobile phone holder can be mounted)
- 6 Hand screw X2

OPERATING INSTRUCTIONS

Product structure diagram.







1 knob

Turn the knob clockwise to adjust the brightness of the light.


Double-click the knob switch to enter the colour temperature mode

Plashing Button / Indicator Light

Press and hold to enter flash mode, release to pause the flash.

On/Off

Push the switch to ON position, automatically detect the power, the indicator light will run a circle and stop in the power position, if low p ower, please charge after use



4 DC charging port Charging voltage 12V 2A

6 1/4 screw hole

Expandable mounting bracket with 1/4 thread connector

ON / OFF

Push the switch to 'ON'.

Automatically detect the power after switching on, the 2 indicator light will be red running around after the red light stops in the power position, low power when the red light flashes, please charge first after use

2 Long press to flash mode Release to stop flashing

3 2700K-7000K colour temperature adjustment

Double-click the knob switch to enter the colour temperature mode, clockwise direction to adjust the cold light, counterclockwise direction to adjust the ambiguous light, adjust the completion of the double-click to return to the


Push to switch between warm and cold light

0-100% brightness adjustable

Turn the knob clockwise to adjust the brightness of the light, this time the light will be in accordance with the % ratio of light, turn counterclockwise when the brightness is dimmed




When charging, press % to flash the light sequentially, full of red light always on



Lights up after


power on

Charging time



FULLY CHARGED

BRACKET DESCRIPTION



- 1/4 screw hole, fits 5, locks bracket to light.
- Expandable to mount any tripod device with 1/4 screws
- 3 With 6 hand screws, the camera can be mounted to the bracket with a locking mechanism.
- Expandable to mount any tripod device with 1/4 screws

WARNING

- Keep this product out of the reach of children in a safe place.
- Please use the original parts correctly.
- Before each use, please be sure to check whether the installation is stable, to prevent accidents during use.
- Store in a cool, dry place, prohibit exposure to the sun, waterproof



MARNING

- 1: Align the bracket to the bottom of the light first and tighten the screw by hand
- 2: The camera is set up on the bracket and screwed in by hand.
- 3: Can be expanded to install any equipment with 1/4 interface according to the use of demand

Before use, please carefully check whether the installation is stable or not.



WARNING

- 1: Align the bracket to the bottom of the light first and tighten the screw by hand
- 2: The camera is set up on the bracket and screwed in by hand.
- 3: Can be expanded to install any equipment with 1/4 interface according to the use of demand

Before use, please carefully check whether the installation is stable or not.

40SHB is a COB 40W, dual colour temperature 2700-7000K adjustable, colour rendering index ≥96, burst flash, along the vintage flash styling of the constant light, mobile phone / camera can be used!

• 2700K - 7000K DUAL COLOUR TEMPERATURE

Knob-adjustable infinitely dimmable, high display index to restore true colours

WITH SILICONE SOFTBOX

The soft light amplitude is suitable, the light is soft and not harsh

0%-100% BRIGHTNESS ADJUSTABLE

Turning the adjustment knob, the brightness change range is 0-100%.

SPECIFICATION

MODEL:	40SHB
TYPE:	COB 40W
Colour temperature:	2700K-7000K
Jadeite thumb ring:	≥ 96
Batteries:	4 x 18650 14.8V (2600mAh)
Charging Voltage:	12V 2A
Duration of use:	Approx. 1 hour (when used at maximum brightness)
Adjustment range:	Brightness adjustment 0%-100%
Number of beads:	Total 192 pcs
Bead Voltage:	36 ~ 68V
Bead Current:	1100mA

INSTRUCTIONS | NOTES

This manual provides information on the proper use and storage of the product and accessories, and assists the user in dealing with questions about their use and in understanding the safety precautions to be taken.

PLEASE READ CAREFULLY

When handing the product over to another person, be sure to include this manual, heed all warnings and follow all instructions in the manual.

2 YEAR WARRANTY DESCRIPTION

The warranty, which applies to all purchasers from our authorised dealers, covers any defects caused by production, as well as failures in the course of normal use, excluding physical damage, natural disasters (fire, flood, earthquake lightning, etc.) and chemical corrosion, unauthorised repairs, replacement of components during handling, collisions at the site of the installation and other failures due to human or force majeure reasons. and damage, or the manual Any malfunction caused by acts expressly prohibited by the instruction manual

ACCESSORY DESCRIPTION

Mobile phone clip, camera frame, hand screws and other accessories are consumables (not in the 2-year warranty), after use, please confirm whether there is aging, damage and other conditions of this phenomenon is normal wear and tear, in order to use the convenience of please contact the dealer in time to buy new parts replacement!

MAINTENANCE METHODS

Please use a soft sponge, soft cloth, dry cloth to clean the product regularly, do not use bleach, wire ball wipe, wipe clean and keep the product dry.

For more information on LENSGO product features, Please visit **WWW.lensgo.net**



- Do not touch the COB lamp beads with your hands to prevent burning hands
- This product is a precision instrument, please avoid dropping it when using it.
- Contact authorised service personnel when repairs are required
- It is recommended to use the original LENSGO cables. Any damage to this product caused by the use of non-Longsong original accessories is not covered by our warranty. Any damage to this product is not covered by our warranty.
- Please clean the product with a soft, dry cloth.
- This specification is based on our rigorous testing. Design and specifications are subject to change without notice
- Please keep it in a safe place, read this instruction manual carefully, and observe all precautions
- Before use, please check whether the installation is stable, to prevent accidents during use.
- Please switch off the product after charging, in order to protect the safety and life of the battery, try not to use it during charging. use the product during charging.
- Do not cover the ventilation holes when using the silicone softbox.

CERTIFICATE OF CONFORMITY


PRODUCT NAME::	
MODEL:	
INSPECTION DATE:	QUALIFIED
INSPECTOR:	














www.lensgo.net

Use your phone's camera or browser to scan the QR code for product support and user guide.

OR PLEASE VISIT: https://www.lensgo.net/, and click on the "User Guide" menu.





JIAZHIYING PHOTOGRAPHY EQUIPMENT CO., LTD.

Address: Room 201, Building C, No. 8 Fengqi Road, Fucheng'ao Community,

Pinghu Subdistrict, Longgang District, Shenzhen, China

Web: https://www.lensgo.net/

Executive Standard: Q/LYJ004-2018

Facebook: Lensgotech

